



# PUMP-SOUND LEVEL TEST



## noisy level result

A.20L=FRONT54.3 SIDE51.9 B.40L=FRONT45.9 SIDE43.3 C.60L=FRONT45.5 SIDE45.3

D.100L=FRONT56.3 SIDE51.9 E.FRONT160L=56 SIDE52.8



## ANECHOIC ROOM

